



# PEATSA

Lauro Aguirre No.32-203 . Col. Agricultura . México, D.F. 11360

Tels: 5342-1586 . 5341-8757

contacto@peatsa.com

www.peatsa.com

Messenger: redes\_peatsa@hotmail.com



## 700006026

### KIT DE CONECTORIZACION DE FIBRA OPTICA

#### 10.1. Tool Kits for Epoxy Installation Method

The 1032B5 and 1032B6 tool kits contain tools needed to field mount STII+ and SC fiber connectors on 3.0mm cords and 0.9 mm buffered fiber using the epoxy method. To install LC connectors requires the addition of the D-182905 Upgrade kit. The 1032B6 Tool Kit contains the same tools and materials as the 1032B5 Tool Kit except the 200A Curing Oven is replaced by the 200A1 Curing Oven for use internationally. The 200A1 oven operates on 220 V 50 Hz. Replacement Material ID for the 200A1 oven is 700008048 and is replaced in quantities of one each.

#### 1032B5 Tool Kit (700006026) / 1032B6 Tool Kit (700005960)

Kit Quantity	Description
1	1510B Crimping Tool
1	300B Microscope
1	1510A Polishing Tool
12	600B Connector Holders
1	700A Stripping Tool
1	1026A Heat Strip Tool
2	971A-1 Holder Blocks
1	975A Cleaving Tool
1	Scissors
1	6-inch Scale
1	Alcohol Bottle
1	Glass Plate
1	Stripping Tool (R4366)
1	Instruction Manual
15	Micro Clips (1043A)
1	200A Curing Oven/or 200A1
12	SC Curing Fixtures
2	Modified SM/MM SC Grips
1	Rubber Polishing Pad
1	1039B Cut-Length Template